




Pos.	Belt cleaner	Belt width – BW* (mm)	Belt speed – BS (m/s)	Pulley diameter – (mm)
1	ABC-ONE90	500-2000	< 3.5	300-600
2	ABC-ONE70	500-2000	< 3.5	300-600
3	ABC95	500-2000	< 3.5	350-600
4	ABC90	500-2000	< 3.5	350-600
5	ABC70	500-2000	< 3.5	350-600
6	ABC-HMS	500-2000	< 3.5	300-800
7	ABC90-HD	500-2000	< 4.5	600-1000
8	ABC70-HD	500-2000	< 4.5	600-1000
9	ABC90-HD-L	600-3000	< 6.0	800-1600
10	ABC90-HD-XL	700-3300	< 6.0	1000-2000

* Other widths available upon request

Description	Hardness	Material/Application
PU70 	70 Sh A / 65 Sh D (Patented)	Super-soft hardness for abrasive materials in mining and aggregates. Especially good for wet and sticky applications (e.g. iron ore, granite, clay)
PU90 	90 Sh A	Standard hardness in the industry for mining and aggregate applications. For less abrasive materials (e.g. limestone, lignite, soft ores/stone).
PU95 	95 Sh A	Hard PU mainly for pulp and paper, wood handling and saw mills, and other non-abrasive materials.
HMS 	Extra-fine tungsten carbide HV30-1600	For cutting and abrasive materials like recycled glass, crushed flintstone, etc. Also good for sticky materials.